


SLG - Photo Installation Report @ 251




Wall Penetration (Auditorium side and Booth side- above ceiling) - JBox Cover (booth side)



Electrical Conduit from the ceiling and connection to SLG rack



Ceiling AP installation (Lights on and Lights off)



AP black cover mounted on the ceiling grid